



P. O. Box 2847, Commercial Station, Springfield, Mo. 65803 417 862-075

Sonderson # Silkeffer

Ponte to Clot

March 31, 1983

Mr. John J. Franke Regional Administrator U.S. Environmental Protection Agency-Region VII 324 East 11th Street Kansas City, Missouri 64106

Dear Mr. Franke,

This letter is to inform you of a reported chemical spill per 40CFR265.56(j). The information which you require is as follows:

265.56 (j) (1) Owner: Litton Industries, Inc.
360 North Cresent
Beverly Hills, California 90210

- 265.56 (j) (2) Facility: Litton-Advanced Circuitry Division 4811 West Kearney Springfield, Missouri 65803 417-862-0751
- 265.56 (j) (3) On March 26, 1983, at 3:00 p.m. approximately 100 gallons of chrome sulfuric acid leaked from a double lined polypro tank into a concrete sump. The acid solution then attacked the concrete sump causing a hole to develope in the floor. The leakage thru the sump allowed this solution to enter the soil immediately under the building.
- 265.56 (j) (4) The chrome sulfuric acid bath consisted of 1-1/4 lbs. per gallon chromic flakes and 30% sulfuric acid in water. There was approximately 100 gallons of solution in the tank when the leak developed.
- 265.56 (j) (5) There were no injuries.
- 265.56 (j) (6) To minimize the environmental impact, the area of the leak was treated as follows:
  - a) All standing solution, approximately 20 gallons, was pumped to a safe container for disposal.
  - b) The remaining solution was neutralized with MacDermid 9080 Neutralizer to convert  ${\rm Cr}^{+6}$  to  ${\rm Cr}^{+3}$  and adjust the pH.



## 265.56 (j) (6) Cont'd

- c) The area was then covered with lime to aid neutralization of the acid.
- d) The hole in the sump was then packed with sand and capped with concrete.

It must also be pointed out that since the leak occurred to an area under our plant, the protective covering offered provided by 120,000 ft. of concrete will prevent any leaching of the spill further than the local area of the leak.

265.56 (j) (7) The approximately 20 gallons of chrome sulfuric acid which we removed from the sump was neutralized using MacDermid 9080. The liquid was then placed in a special double lined drum awaiting disposal at Chemical Waste Management Inc. in Emelle, Alabama.

All emergency equipment was cleaned prior to the storage of the equipment.

Sincerely,

Jim/Dow

Emergency Coordinator

JD/bs

CC: Mr. D. Edwards, ACD

Mr. Gerald Lucey - Litton

Mr. John Nixon - Regional Administrator, DNR

Mr. Burt McCullough - Environmental Specialist, DNR

· 技术区外企业有数